

Mile High Septic Solutions

Service Ticket

J1459 Real Estate Inspection for
Annie Kinsella (Complete)

Thursday

Pumping - Septic Real Estate
inspection

Jun 26, 2025

7:00AM to 9:00AM EDT

Driver 4

Jun 26, 2025 12:57PM EDT

Service address (#S23)

Site 4
111 S Wadsworth Blvd
Lakewood, CO 80226
Territory Golden/West Denver

Site Contacts

- Claudine O’Kon, Guy with a key, osinski.preston@little.com, +17632751778

System Specifications

Service Details

Type:	septic	Depth (feet):		Hose Length Used (feet):	75
Gallons:	3500	Hose (feet):	100	Truck:	Ford
Construction:	concrete			License/Certification Number:	#123456
System Notes:				Permit Number:	#123456
Tank Information				Amount Pumped (gallons):	1500
Tank Size (gallons):	1500			Tank Condition	
Recommended Next Cleaning:	2028-06-26			Baffle Wall Condition:	good
Tank Location:	backyard next to barn			Outlet Filter Cleaned:	Yes
Tank Material:	concrete			Solids in Tank:	Yes
Install Date:	2025-06-26			Inlet Baffle:	good
Tank Inspection				Outlet Baffle:	good
Does It Use Risers:				Outlet Tee:	good
Digging Required:				Inlet Tee:	good
Digging Depth (inches):				Effluent Filter:	goos
Tank/Water Level:				Sludge Layer:	high
Access Point:				Scum Layer:	high
Roots:				Lids:	
Leach Line Tested:				Lid Count:	1
Passes Inspection:				Lid #1:	
				Lid Material:	concrete
	Lid Condition:	goos			
	Digging Required:	Yes			
	Digging Depth:	36			
	Disposal Site:	Metro Wastewater Reclamation			

Driver Completion Notes:

all good

Customer (#C4)

Annie Kinsella
5161 W 120th Ave.
Broomfield, CO 80020

Phone

- Primary (303) 123-4700

Disclaimer

Terms and Conditions. We are not liable for damages to your property.

A handwritten signature in black ink, consisting of a series of loops and a final horizontal stroke.

2025-06-26

Date

Customer Signature